


## Test Modul PE50R



The test module PE50R can be used for testing and calibrating of our capacitive moisture meter PD5-AL.

**Using:**

have a look to the sensor, it has to be clean and dry.

Hold the instrument into the air and switch it on.

Adjust the mentioned material setting. Prick the sensor into the test module, hold the sensor with the testmodule free into the air, read of the display value and compare it with the rated value.

meter type	adjustment	rated value	comment:
PD5-AL	Material 1	9,2±0,2	