

Feuchtigkeitsmessgeräte Moisture Meter Humidimètre



Test Modul PE30



The test module PE30 can be used for testing and calibrating of our capacitive moisture meters.

Using:

have a look to the sensors, they have to be clean and dry. They must be parallel in one line.

Hold the instrument into the air and switch it on.

Adjust the mentioned material setting, press the sensor on the test module, in the middle, as shown in the picture. (pressing pressure approx. 50 N). Read of the display value and compare it with the rated value.

The instruments AD4A, DM4A and DS4A can be calibrated (code 97). At other instruments we recommend a new calibration procedure through a authorised person.

meter type	adjustment	rated value	comment:
O11		42% ± 1%	
AD4A	code 97	800	calibration possible, follow the instruction manual!
DM4A	code 97	200	calibration possible, follow the instruction manual!
DOMA	woodgroup 0	10,0% ± 0,2%	
DS4A	code 97	200	calibration possible, follow the instruction manual!
H24/70	0	15% ± 0,5%	
HD1	00,0	11,0% ± 0,5%	
HD5	H1	12,0% ± 0,5%	
P12/20	3	6,0% ± 0,5%	
PD1	00,0	7,2% ± 0,5%	
PD2	P2	6,2% ± 0,4%	